

SECRET

OUT52446

1

SECRET 122135Z

05 DEC 12 21 47Z

25X1

1. CAMERA B 8 WAS USED IN MISSION 3790 FLOWN ON 10 DECEMBER 1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

13 DEC 1963

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: INBOARD EDGE FOG OCCURS INTERMITTENTLY THROUGHOUT THE MISSION. A PLUS DENSITY LINE 3.3" FROM AND PARALLEL TO THE OUTBOARD EDGE IS PRESENT FROM HEAD TO TAIL. EDGE STATIC IS NOTED ON FRAME 1137. FRAME 1166 CONTAINS A MANUFACTURER'S SPLICE WHILE HEAT SPLICES APPEAR ON FRAMES 686, 1065, AND 1510. A PLUS DENSITY STREAK CAUSED BY A FORMAT REFLECTION IS PRESENT AT THE OUTBOARD EDGE OF THE FORMAT THROUGHOUT THE MISSION. A MINUS DENSITY STREAK AT AND PARALLEL TO THE INBOARD EDGE OCCURS ON FRAME 8 TO 1375.

Grace (File)

C. 9L SIDE: SEVERAL ROWS OF FAINT MINUS DENSITY DOTS APPEAR INTERMITTENTLY ALONG THE MAJOR AXIS ON THE FIRST 100 FRAMES. THERE IS A MANUFACTURING SPLICE WITH ASSOCIATED PLUS AND MINUS DENSITY STREAKS ON FRAME 1398.

D. BOTH SIDES: THERE ARE 2314 TITLED FRAMES ON EACH SIDE OF THIS MISSION.

1

25X1

SECRET

Declassification Review by NGA/DoD

GROUP 1
Excluded from automatic
downgrading and
declassification

-2-

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD. TWO COPIES OF ROLL 3 WERE RECEIVED AND NO COPY OF ROLL 4 ON THE 9R SIDE.

B. PI SUITABILITY IS GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 25 PER CENT OF THIS MISSION.

S E C R E T

-END OF MESSAGE-

1